

Facility Safety Inspection Fire & Life Safety / Environmental Health Licensed Day Care Programs Compliance Plan

Provider's Name: **Hamlin Community Daycare Center**

City: **Hayti**

Provider Number: **011515290**

Inspector: **Charles Schmidt**

Date of Inspection: **09/26/2018**

Time of Inspection: **4:19 PM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

A. FIRE AND LIFE SAFETY

9. In storage rooms, are combustible materials maintained at least 2 feet below the ceiling or 18 Inches below sprinkler head deflectors? 67:42:10:18

<p>Corrections To Be Made:</p> <p>Combustible materials were less then 2 feet from the ceiling.</p> <p>**All storage items were moved and placed at least 2 freet below the ceiling.**</p>	<p>Agency Action:</p> <p>Compliance Plan</p> <table style="width: 100%;"> <tr> <td style="width: 50%;">Suggested Completion Date:</td> <td style="width: 50%;">Actual Completion Date:</td> </tr> <tr> <td style="text-align: center;">10/26/2018</td> <td style="text-align: center;">10/01/2018</td> </tr> </table> <p>Status: Corrected</p>	Suggested Completion Date:	Actual Completion Date:	10/26/2018	10/01/2018
Suggested Completion Date:	Actual Completion Date:				
10/26/2018	10/01/2018				

Amy Fuller

Provider Signature

09/26/2018

Date

Charles Schmidt

Inspector Signature

09/26/2018

Date