

Facility Safety Inspection Fire & Life Safety / Environmental Health Licensed Day Care Programs Compliance Plan

Provider's Name: **Hanson CLC- After school program**

City: **Alexandria**

Provider Number: **014510700**

Inspector: **Carrie Lewis**

Date of Inspection: **08/12/2020**

Time of Inspection: **1:30 PM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

B. ENVIRONMENTAL HEALTH

65. Is there a fenced outdoor play area? Does the fenced area appear to allow for 50 square feet per child during each scheduled recess time? 67:42:11:02

<p>Corrections To Be Made:</p> <p>The outside play area does not have a fence around the south side of the play area.</p> <p>*A letter of notification was issued giving the Provider additional time to complete this requirement.</p>	<p>Agency Action:</p> <p>Letter of Notification</p> <table style="width: 100%;"> <tr> <td style="width: 50%;">Suggested Completion Date:</td> <td style="width: 50%;">Actual Completion Date:</td> </tr> <tr> <td>08/19/2020</td> <td></td> </tr> </table> <p>Status: Pending</p>	Suggested Completion Date:	Actual Completion Date:	08/19/2020	
Suggested Completion Date:	Actual Completion Date:				
08/19/2020					

Ann Bartscher

Provider Signature

08/12/2020

Date

Carrie Lewis

Inspector Signature

08/12/2020

Date