

# Family Day Care Inspection Compliance Plan

Provider's Name: **Michelle Sehr**

City: **Canton**

Provider Number: **018042483**

Inspector: **Shannon Terhark**

Date of Inspection: **04/15/2020**

Time of Inspection: **9:45 AM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

## C. Health & Safety Features of the Home - Indoor Environmental Observations

79. If there is more than 44 inches between the floor and the bottom of the window, is there a stable and permanent platform underneath the window to bring the distance to 44 inches or less? 67:42:03:11.03

Corrections To Be Made:

**The egress window is 48" from the ground. A stable platform is needed under the egress window.**

**\*\*\*A platform has been placed under the window.**

Agency Action:

### Compliance Plan

Suggested  
Completion  
Date:

**05/15/2020**

Actual  
Completion  
Date:

**04/28/2020**

Status: **Corrected**

**Michelle Sehr**

Provider Signature

**04/15/2020**

Date

**Shannon Terhark**

Inspector Signature

**04/15/2020**

Date