

Facility Safety Inspection Fire & Life Safety / Environmental Health Licensed Day Care Programs Compliance Plan

Provider's Name: **St. Agnes Red and Gold**

City: **Vermillion**

Provider Number: **019524365**

Inspector: **Stacy Wildermuth**

Date of Inspection: **03/15/2019**

Time of Inspection: **9:15 AM**

The items listed below are those that the provider was not in compliance with at the time of the inspection.

B. ENVIRONMENTAL HEALTH

44. Is the water temperature at children's hand washing sinks maintained at 120 degrees or lower?
67:42:11:09

<p>Corrections To Be Made:</p> <p>Hot water temperature at the hand sinks measured at 126 degrees during inspection. Water temperature must be maintained at 120 degrees or below.</p> <p>Correction: The hot water temperature was adjusted to ensure it is maintained 120 degrees or lower.</p>	<p>Agency Action:</p> <p>Compliance Plan</p> <table style="width: 100%;"> <tr> <td style="width: 50%;">Suggested Completion Date:</td> <td style="width: 50%;">Actual Completion Date:</td> </tr> <tr> <td style="text-align: center;">03/22/2019</td> <td style="text-align: center;">04/08/2019</td> </tr> </table> <p>Status: Corrected</p>	Suggested Completion Date:	Actual Completion Date:	03/22/2019	04/08/2019
Suggested Completion Date:	Actual Completion Date:				
03/22/2019	04/08/2019				

Jessica Schulte

Provider Signature

03/15/2019

Date

Stacy Wildermuth

Inspector Signature

03/15/2019

Date